

Triumph T100A T120/T140 Twin Cylinder Camshaft

Part No	Aplication	O.E.	Dura	ation	Cam	Lift	Timing		Full Lift	Valve Clear		Price	Material
		Part No	In	Ex	In	Ex	Open	Close	IN atdc	In	Ex	Ex VAT	Type
TRI/295/IN	T120 IN Standard Cam		TBA	TBA	0.295	0.295				0.010	0.012	£95.00	Billet
	Thunderbird Profile											£30.00	Repro
Notes	New Billet Cams Manuafctured from EN4	0 B Nitridin	g Steel (F	Regrind m	ax wear	on top of	cam lobe	0.010 Th	nou)				
TRI/295/EX	T120 EX Standard Cam		TBA	TBA	0.295	0.295				0.010	0.012	£95.00	Billet
	Thunderbird Profile											£30.00	Repro
Notes	New Billet Cams Manuafctured from EN4	0 B Nitridin	g Steel (F	Regrind m	ax wear	on top of	cam lobe	0.010 Th	nou)				
TRI/3134/IN	T120 IN Standard Cam	3134	312	312	0.315	0.315	46/86	86/46	TBA	0.010	0.012	£95.00	Billet
	3134 Profile											£30.00	Repro
Notes	New Billet Cams Manuafctured from EN40 B Nitriding Steel (Regrind max wear on top of cam lobe 0.010 Thou)												
TRI/3134/EX	T120 EX Standard Cam	3134	312	312	0.315	0.315	46/86	86/46	TBA	0.010	0.012	£95.00	Billet
	3134 Profile											£30.00	Repro
Notes	New Billet Cams Manuafctured from EN40 B Nitriding Steel (Regrind max wear on top of cam lobe 0.010 Thou)												
TRI/300/348IN	T120 IN Race Cam		300	300	0.348	0.348	48/72	70/50	0.116	0.010	0.012	£95.00	Billet
												£30.00	Repro
Notes	New Billet Cams Manuafctured from EN40 B Nitriding Steel (Regrind max wear on top of cam lobe 0.010 Thou)												
TRI/300/348/EX	T120 EX Race Cam		300	300	0.348	0.348	48/72	70/50	0.109	0.010	0.012	£95.00	Billet
												£30.00	Repro
Notes	New Billet Cams Manuafctured from EN40 B Nitriding Steel (Regrind max wear on top of cam lobe 0.010 Thou)												

Triumph T150/T160 Triple Cylinder Inlet/Exhaust Universal Camshaft

Part No	Aplication	O.E.	Duration		Cam	Lift	Timing		Full Lift	Valve Clear		Price	Material
		Part No	ln	Ex	In	Ex	Open	Close	IN atdc	In	Ex	Ex VAT	Type
T150/T160	T150/T160 Standard Cam	T140			0.315	0.315	46/86	86/46		0.010	0.012	£168.00	Billet
												£40.00	Repro
Notes	New Billet Cams Manuafctured from EN40 B Nitriding Steel (Regrind max wear on top of cam lobe 0.010 Thou)												

Notes:-

 ${\bf Reground\ Camshafts\ customers\ own\ cams\ ground\ and\ heat\ treated\ Case\ Harden\ Early\ Cams,\ Nitride\ Late.}$

Only grinding extisting profiles on the cams Max wear on cam 0.010"

Cam Follower Reclamation Service. We regrind and Lap and Polish T100/T140 Cam Followers.

Working on customer own cam followers This is not an exchange service.

Triumph Additional Components

Part No	Description						
TRI/T120/40	4 x Cam Followers ground lapped and polished	£40.00					
TRI/T120/40 NEW	4 x New Cam Followers	£72.00					





Address: Farnborough Way, Farnborough, Kent, BR6 7DH, United Kingdom

Telephone: +44 (0)1689 857 109 Fax: +44 (0)1689 855 498 E-Mail: info@newman-cams.com Website: www.newman-cams.com